


belinda-melissa



- One-hole sink mixer with swivelling spout complete with:
- aerator M22x1
- set of 2 stainless steel hoses 3/8"G
- One-hole sink mixer with swivelling spout complete with:
- aerator M22x1
- set of 2 stainless steel hoses 3/8"G

FBLV 180

- CR- Chrome | Chrome
- CO- Chrome + gold finish | Chrome + gold finish
- BR- Bronze | Bronze
- RM- Copper | Copper

ARTICOLO ARTICLE

FBLV 180..

- with spout - 210mm
- with spout - 210mm

RAPPORTO PROVA PORTATA FLOW RATE REPORT

	Uscita outlet	Pressione / Pressure (bar)									
		0,5	1	1.5	2	2.5	3	3.5	4	4.5	5
Portata / Flow rate (l / min)		6.18	8.85	11.06	12.78	14.32	15.83	17.16	18.42	19.54	20.72


DOCUMENTI TECNICITECHNICAL DOCUMENTS



ESPLOSO
RICAMBI
FBLV 180



belinda-melissa



- One-hole sink mixer with swivelling spout complete with:
- aerator M22x1
- set of 2 stainless steel hoses 3/8"G
- One-hole sink mixer with swivelling spout complete with:
- aerator M22x1
- set of 2 stainless steel hoses 3/8"G

FME 181

- CR- Chrome | Chrome
- CO- Chrome + gold finish | Chrome + gold finish
- BR- Bronze | Bronze
- RM- Copper | Copper

ARTICOLO ARTICLE

FME 181..

- with spout - 210mm
- with spout - 210mm

RAPPORTO PROVA PORTATA FLOW RATE REPORT

	Uscita outlet	Pressione / Pressure (bar)									
		0,5	1	1.5	2	2.5	3	3.5	4	4.5	5
Portata / Flow rate (l / min)		6.73	8.96	10.78	12.39	13.76	15.07	16.17	17.29	18.33	19.32


DOCUMENTI TECNICI TECHNICAL DOCUMENTS



ESPLOSO
RICAMBI
FME 181



belinda-melissa



- Wall sink mixer bridge model with swivelling spout complete with:
- aerator M22x1
- set of 2 S-wall-unions 1/2"x3/4"G and wall-plates
- Wall sink mixer bridge model with swivelling spout complete with:
- aerator M22x1
- set of 2 S-wall-unions 1/2"x3/4"G and wall-plates

ARTICOLO ARTICLE

FBLV 161..

- with "S" spout - Ø18x180mm
- with "S" spout - Ø18x180mm

FBLV 161

- CR- Chrome | Chrome
- CO- Chrome + gold finish | Chrome + gold finish
- BR- Bronze | Bronze
- RM- Copper | Copper

DOCUMENTI TECNICI TECHNICAL DOCUMENTS



ESPLOSO
RICAMBI

FBLV 161

